ONERENT · QUICK USER GUIDE

Inspection camera WÖHLER VIS 350 (20 m)

A short guide to the inspection camera with 20 m cable: preparation, inspecting a pipe and recording images.



1. Before you start

- Check that the kit contains everything listed in the hand-over record.
- Check the battery charge and that the SD card is in the monitor.
- Connect the monitor to the cable reel and make sure the camera head is clean.

2. Inspection

- Switch on the monitor and set the LED brightness.
- Push the cable slowly into the pipe or flue; the counter shows the length inserted.
- Use the camera head control to turn the view towards walls and joints.

3. Recording

- Record video or save photos to the SD card — note the distance to the damage.
- When pulling the cable out, wind it back on the reel evenly, without kinks.

4. Tips

- Do not force it: if the cable gets stuck, pull it back a little and try again.
- In very sharp bends the camera may not pass — do not over-bend the cable.

5. Safety and care

- The camera head is waterproof, but the monitor and reel are not; keep them away from water.
- After work, clean the cable and head with a damp cloth, especially after sewers.
- If the equipment does not work properly, stop using it and call us: +371 26537465.

6. Returning

- Return the equipment to Slokas iela 52N clean and complete — with all accessories listed in the hand-over record.
- Before returning, copy your recordings and delete them from the SD card.

Based on the Wöhler manufacturer’s instructions. The full manual is included with the device.